

FUEL LIFT PUMP



Fuel Lift Pump 2 hole fixing

Rating: Not Rated Yet
[Ask a question about this product](#)

Manufacturer: [RIDESA](#)

Description

TRACTOR MODEL COMPATABILITY

Landini
Agricultural Tractor - 500 Series
8500
Massey Ferguson
Agricultural Tractor - 1000 N.A. Series
1100
Agricultural Tractor - Articulated Series
1200
Agricultural Tractor - Landini Series
1014, 1114
Combine Harvester
500 Combine, 510 Combine, 520 Combine, 525 Combine, 620 Combine, 625 Combine
Perkins
6.354 Series
A6.354, A6.354.1, A6.354.2, AT6.354.2, T6.354, T6.354.2
White/Oliver
1850, 2-105, 2-85

OEM

Landini
2641372, 2641A064, 3637309M91, 4222093M91, ULPK0007
Massey Ferguson
2641372, 2641378, 2641A064, 3637309M1, 3637309M91, 4222093M91, 892632M91
Not Specified
2614372, 3637 309M91, 4222093M91
Perkins
2641372, 2641A064